

## STEAM SLAB

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A D 0 8 . 6 . 5 . 1 0 0 0 5	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.		
3. Generator's Name and Mailing Address Douglas Aircraft Co. 190th & Normandie Ave. Torrance, CA 90502			A.State Manifest Document Number 84924329				
4. Generator's Phone ( 213 533-6677			B.State Generator's ID				
5. Transporter 1 Company Name J. C. Liquid Waste Disposal		6. US EPA ID Number C A D 0 5 . 8 . 0 . 1 8 3 6 7		C.State Transporter's ID 64164 ✓			
7. Transporter 2 Company Name		8. US EPA ID Number		D.Transporter's Phone 213 268-3137			
9. Designated Facility Name and Site Address Triple J 3650 E. 26th St. Vernon, CA		10. US EPA ID Number C A T 0 8 . 0 . 0 . 3 . 3 6 8		E.State Transporter's ID			
				F.Transporter's Phone			
				G.State Facility's ID			
				H.Facility's Phone			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)			12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Hazardous Waste liquid NOS ORM-E NA9189			001	TT	05000	G	221
b.							
c.							
d.							
J. Additional Descriptions for Materials Listed Above Alkaline Soap 5% Grease 2% Oil 3% WATER 90%			K.Handling Codes for Wastes Listed Above 01				
15. Special Handling Instructions and Additional Information Guide #31 Use gloves, goggles, respirator - Do not go near open flame or inhale fumes. If rejected, return to Douglas							
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.							
Printed/Typed Name Donald C. Gerber			Signature Donald C. Gerber		Date 04/10/86		
17. Transporter 1 Acknowledgement of Receipt of Materials			Signature Santos Ybarra		Date 04/10/86		
Printed/Typed Name SANTOS YBARRA W/056457			Signature		Date		
18. Transporter 2 Acknowledgement of Receipt of Materials			Signature		Date		
Printed/Typed Name			Signature		Date		
19. Discrepancy Indication Space							
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.							
Printed/Typed Name ANNELINE OSTERBERG FOR TRIPLE J			Signature Anneline Osterberg		Date 04/10/86		



## STEAM SLAB

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>C A D 0 8 6 5 1 0 0 0 5</b>		Manifest Document No.		2. Page 1 1 of 1		Information in the shaded areas is not required by Federal law.		
3. Generator's Name and Mailing Address <b>Douglas Aircraft Co. 190th &amp; Normandie Ave. Torrance, CA 90502</b>				A.State Manifest Document Number <b>84924329</b>		B.State Generator's ID				
4. Generator's Phone ( <b>213 533-6677</b> )				6. US EPA ID Number <b>C A D 0 5 8 0 1 8 3 6 7</b>		C.State Transporter's ID <b>64164</b> ✓				
5. Transporter 1 Company Name <b>J. C. Liquid Waste Disposal</b>				8. US EPA ID Number		D.Transporter's Phone <b>213 268-3137</b>				
7. Transporter 2 Company Name				10. US EPA ID Number		E.State Transporter's ID				
9. Designated Facility Name and Site Address <b>Triple J 3650 E. 26th St. Vernon, CA</b>				10. US EPA ID Number <b>C A T 0 8 0 0 3 3 5 8</b>		F.Transporter's Phone				
						G.State Facility's ID				
						H.Facility's Phone				
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)						12.Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. <b>Hazardous Waste liquid NOS ORM-E NA9189</b>						<b>001</b>	<b>TT</b>	<b>05000</b>	<b>G</b>	<b>221</b>
b.										
c.										
d.										
J. Additional Descriptions for Materials Listed Above						K.Handling Codes for Wastes Listed Above				
<b>Alkaline Soap 5%</b> <b>Grease 2%</b> <b>Oil 3%</b> <b>WATER 90%</b>										
15. Special Handling Instructions and Additional Information <b>Guide #31</b> <b>Use gloves, goggles, respirator - Do not go near open flame or inhale fumes.</b> <b>If rejected, return to Douglas</b>										
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.										
Printed/Typed Name <b>Donald C. Gerber</b>						Signature <i>Donald C. Gerber</i>		Date Month Day Year <b>04/10/86</b>		
17. Transporter 1 Acknowledgement of Receipt of Materials						Signature <i>Santos Ybarra</i>		Date Month Day Year <b>04/10/86</b>		
Printed/Typed Name <b>SANTOS YBARRA W/056457</b>								Date Month Day Year .		
18. Transporter 2 Acknowledgement of Receipt of Materials						Signature		Date Month Day Year .		
Printed/Typed Name								Date Month Day Year .		
19. Discrepancy Indication Space										
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.										
Printed/Typed Name						Signature		Date Month Day Year .		